



Supply

Certificate of Completion

Duct Sealing Performed For:

Residence, Dunn
9300 St Andrews Way
Silver Spring, MD 20901

Overall Sealing Results

When we arrived,
YOUR DUCTS HAD:

527.6 CFM of Leakage, equivalent to a
99.7 Square Inch Hole


This equals 316.6 refrigerators full of air loss every hour.

After we finished,
YOUR DUCTS HAVE:

36.8 CFM of Leakage, equivalent to a
7.0 Square Inch Hole

This corresponds to a **93.0% Reduction in Duct Leakage.**

Note: Duct Leakage results are calculated in Cubic Feet per Minute (CFM) measured at a standard OPERATING PRESSURE of 25 Pa.



Aeroseal Technician Josh

Aeroseal Case ID 3232

Date of Seal 3/20/2017

System Description Gas furnace

Seal Description Clean and seal air ducts

Hardware Gen2

Duct Sealing Performed By:

AEROSEAL
22875 bryant ct
sterling, va 45458
Phone:

AEROSEAL
Duct Sealing From The Inside



Return

Certificate of Completion

Duct Sealing Performed For:

Residence, Dunn
9300 St Andrews Way
Silver Spring, MD 20901

Overall Sealing Results

When we arrived,
YOUR DUCTS HAD:

360.0 CFM of Leakage, equivalent to a
68.0 Square Inch Hole


This equals 216 refrigerators full of air loss every hour.

After we finished,
YOUR DUCTS HAVE:

31.9 CFM of Leakage, equivalent to a
6.0 Square Inch Hole

This corresponds to a 91.1% Reduction in Duct Leakage.

Note: Duct Leakage results are calculated in Cubic Feet per Minute (CFM) measured at a standard OPERATING PRESSURE of 25 Pa.



Aeroseal Technician Josh

Aeroseal Case ID 3232

Date of Seal 3/20/2017

System Description Gas furnace

Seal Description Clean and seal air ducts

Hardware Gen2

Duct Sealing Performed By:

AEROSEAL
22875 bryant ct
sterling, va 45458
Phone:

AEROSEAL
Duct Sealing From The Inside

